


FIG.1



## 3/19





FIG.3



5/19





FIG.5



7/19





FIG.7



9/19



Ø	6					
16	17		18			
64	14	15		16		
64	11	0,	7	13		
	8		9			
16 16 64	9		7			
16	4	4 3				
16	2		က			
Ø		7	_			
¥						

	,				
19	20	Ŋ			
11	18	6			
14	15	16			
11	12	13			
8	6	10			
9	7	8			
4	9				
2	3				
-	N.	**************************************			
<u>~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~</u>					

6 SI=

10/19




FIG. 10

11/19





FIG.11



13/19





FIG.13



15/19







FIG.15







18/19




FIG.19

19/19




FIG.20

S0	0	1	2	3	4	5	6	7	CO	C 1	C 2
S1	8	9	1	1	1 2	1 3	1 4	1 5	ပအ	C 4	C 5
S2	1 6	1 7	1 8	1 9	2	2	2 2	2	C 6	C 7	C 8

FIG.21